

### SCS Accessories Selection Guide

Image	Product No.	Description
	<b>723</b>	Accessory Belt Clip to be used with the Wrist Strap Monitor 725
	<b>724P</b>	Power Supply for Wrist Strap Workstation Monitor 724 and Static Monitor 790
	<b>724VK</b>	Monitor Verification Kit. Verifies the resistance range of the Workstation Monitor 724
	<b>725VK</b>	Monitor Verification Kit. Verifies the resistance range of the Wrist Strap Monitor 725
	<b>732</b>	Replacement Remote Input Jack. 6 ft. (1.8 m) long cord. To be used with Workstation Monitor 724.
	<b>733</b>	Remote Splitter Kit. 6 ft. (1.8 m) long cord. To be used with Workstation Monitor 724.
	<b>740P</b>	Power Supply for Wrist Strap and Footwear Tester 740
	<b>746P</b>	Power Supply for Wrist Strap Tester 746
	<b>790VK</b>	Verification Kit. One 5 ft. (1.5 m) Dual Conductor Cord 2360, one test wrist band socket assembly, and one two-wire male connector with 24 in. (0.61 m) lead wire.
	<b>2380</b>	Monitor/Table Mat Replacement Cord, 6 ft. (1.8 m), with 10 mm snap. Extends from the Wrist Strap Workstation Monitor 724 to the static control worksurface to be monitored. This cord does not have a resistor molded into the snap fastener cap.
	<b>2389</b>	Monitor/Table Mat Interconnect Cord, 10 ft. (3 m), with 10 mm snap. A straight cord with male snap fasteners at each end and no resistors. Used to interconnect two monitored worksurfaces.

### SCS Accessories Selection Guide

Image	Product No.	Description
	<b>3033</b>	Snap Fastener, male, 0.125 in. (3.2 mm) hole, 10 mm diameter. For mats and runners. 1800/8800 Series.
	<b>3034</b>	Snap Fastener, female, 0.125 in. (3.2 mm) hole, 10 mm diameter. For Mats and Runners 1800/8800 series.
	<b>3037</b>	Insulated Bulldog Clip. Fits standard banana plug.
	<b>3038</b>	Uninsulated Alligator Clip. Fits standard banana plug.
	<b>3040</b>	Ground Cord, 15 ft. (4.6 m), with 10 mm snap. Molded-in male snap fastener with integral 1 megohm resistor on one end, solderless terminal on other. Connects all Static Control Mats and Runners to building ground.
	<b>3041</b>	Grounding Kit for Static Protective Hard Laminate includes #10 screw, lock washer, #10 nut, lock washer wing nut, #10 self-tapping screw and one 10 ft. (3.0 m) ground cord. Ground cord has a 1 megohm resistor.
	<b>3042</b>	Wrist Strap Grounding System. Grounds two single conductor wrist straps and conveniently mounts beneath the edge of most work benches. Comes complete with 10 ft. (3.0 m) ground cord.
	<b>3043</b>	Interconnect Cord 5 ft. (3.5 m), with 10 mm snap. Molded-in male snap fastener at each end. Connects all static control mats and runners to each other. Ground cord has a 1 megohm resistor.
	<b>CTA242</b>	This remote terminal connects to WS Aware workstation monitors and provides connection for dual wire wrist straps for an operator and a visitor. Patented plug-in replaceable board with the jacks reduces cost of ownership of the monitor since only one inexpensive board needs to be replaced when the jacks are worn out, instead of the entire terminal.
	<b>CTA243</b>	Before sensitive devices are handled, Big Brother alarms alert the operator to plug-in. Once Big Brother senses that the operator is properly grounded the alarm is silenced. The Big Brother wrist strap terminal makes the WS Aware one of the most intelligent and cost-effective systems on the market today.
No Photo Available	<b>CTA245</b>	Replacement board with jacks for WS Aware remote monitors CTA242 and CTA243.
	<b>FGC150M</b> <b>FGC151M</b>	The low profile beveled cap prevents the cord from being accidentally removed from the mat. A 3/8 in. (10 mm) stud securely snaps to the mat, and at the other end of the 15 ft. (4.5 m) cord is a ring terminal.
	<b>WSGR2</b>	This metal grounding block accommodates two wrist straps and comes complete with mounting hardware. Designed to be mounted under the bench and keep the wrist strap connections safe. The integral 15 ft. (4.5 m) cord ends with a ring terminal. Two 4 mm parking studs hold coiled cords to reduce damage to cords left at the bench. No resistor.